



Midmark Corp.  
60 Vista Drive  
Versailles, OH 45380  
1.800.643.6275  
midmark.com

## Midmark Imaging Software

The computer must be capable of installing .NET 4.8.1. This will automatically be installed as part of the Midmark Imaging installation process, but the computer must be capable of installing it or the software installation will not be able to continue. It is recommended that the operating system be fully up to date to ensure the security of the system.

System Requirements:	Recommended:	Minimum:
Windows Operating System	<ul style="list-style-type: none"><li>Windows 11 Pro or Enterprise (64)</li></ul>	<ul style="list-style-type: none"><li>Windows 10 Pro or Enterprise (32 &amp; 64) Version 21H2 (Build 19044) or Windows Server 2022</li></ul>
Apple Support	<ul style="list-style-type: none"><li>Intel-based Apple hardware running native Windows Platform using Boot Camp</li></ul>	
Processor	Intel i5 (or greater)	Intel i3
Memory	16 GB RAM (or greater)	8 GB RAM
Storage	512GB Hard Drive (or greater)	256GB Hard Drive
Video	32 bit, 1920 X 1080 Resolution Capable	32 bit, 1024 X 768 Resolution Capable
Display	1920 X 1080, 32 true bit color	1024 X 768, 32 true bit color
USB Ports	High Speed USB 3.0	High Speed USB 2.0

A back-up storage device is recommended (DVD, External Hard Drive, other).

**Note:** Windows 10 or 11 Home is NOT recommended. Windows Small Business Server is NOT supported. Any Windows Server acting as a Domain Controller is NOT supported.

For additional information, contact Midmark Imaging Technical Support at 847.415.9800 option 1.

**Note:**

If additional resources or services are running, the Midmark Imaging Software performance may be impacted and could result in not meeting performance expectations. Additionally, as technology changes, it may present an increasing demand for processing power or other resources; as such, the system requirements are subject to change over time.